## THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

## ARIZONA DEPARTMENT OF PUBLIC SAFETY

## STANDARD QUALITY ASSURANCE PROCEDURES INTOXILYZER MODEL 8000

## STANDARD CALIBRATION CHECK PROCEDURE

DATE 12 77 7011 TIME 1871
INTOXILYZER SERIAL # (D-000312 LOGI-
INTOXILYZER SERIAL # O OOO 312 LOCATION 670/ SESTREUX PROPERTIES INTOXILYZER SERIAL # O OOO OR LOCATION 670/ SESTREUX PROPERTIES INTOXILYZER SERIAL # O OOO OR AC.  Pour a standard alcohol concentration solution AC, into a clean dry simulator and assemble the simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach 34°C ± 0.2°C  2. Intoxilyzer 8000 display reads "PUSH BUTTON TO START" made press ENTER.  3. Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After selection is made press ENTER.  4. Air blank completed. 5. Calibration check completed. Test results 0. AC. 6. Air blank completed. 7. Remove printed record. Attach the record to the completed checklist.  SIGNATURE  DPS Form Exh G-2 (Rev 05-04)

INTOXILYZER 8000

Location: 10701 S ESTRELLA Serial Number: 80-000312

Core Version: 8105.48

12/27/2011

18:21:55

\_\_\_\_\_ Standard Lot#: 06011100A1

Last Changed By: M. GUILBAULT #1144 -----

QAS: M. GUILBAULT #1144

GOODYEAR PD

Operator: M. GUILBAULT #1144

GOODYEAR PD

Test

g/210L

-----

Air Blank 0.000 0.100 Cal Check 0.101 Air Blank 0.000

18:22:29 18:22:50

18:23:20

Preventative Maintenance Performed -- Timer Reset